

EQ NOT LISTED IN CSG

COMCAST GL # K-34 LOCKER #

2005
PITTSBURGH LOCKUP

Conv. Returned

1-24-05

COMCAST

CONVERTER TEST FORM

FDDLSSTTC TICKET #

TS-745

HUB #

#

Account #

8773100010031033

Converter #

Name:

JOE/EDWARDA-AMAZON

Converter Type:

Address:

333 COHANST ST

Received From:

City:

TAUNTON

State/Zip

SSN#:

Generated From:

HE-04-ATT123080

T1M3706531A2

JETCOOLD DPV-7

FIELD - TECH #3455

MA 02780

AUDIT Tech #3455

EXHIBIT

B

All Pay Channels

Currently Receiving Unauthorized Service:

YES 80 HBO

Pre 4 Point Test

CODES RECEIVED

E=CO F2=OF,1F,2F,3F,4F,5F,6F,7F,

8F 9F

OTHER NOTABLE FEATURES

chip installed in box.

OUTSIDE CONVERTER APPEARANCE

YES

Security Tabs Missing

NO

Outside Screws Missing

YES

Damaged Memory

NO

Marks Around Outside Screw

YES

Wires Cut

YES

Tampered Codes

INSIDE CONVERTER APPEARANCE

ADP Module Forced Open (Regency Boxes Only)

ADP Module Cover Missing (Regency Boxes Only)

Scratches/Marks on Key Chips (Regency Boxes Only)

Jumper Wires Still In Place (Regency Boxes Only)

Scratches/Marks on Legs of Key Chips

Missing Prom #

4 Point Test

Testing Point

Codes/Comments

Pass/Fail

1. Check Video on converter (e.g. channel 5 or PPV barker on all channels.)
2. Converter has 210 code or higher
3. Converter has H-1 or H8 code, or tunes 01-99 or 01-128 consecutively.
4. Converter does not initialize (i.e. an addressable hit)

N/A

N/A

/

/

Of the 4 points, how many points does it have?

Test Completed By:

Paul Mancuso

Date Completed On:

1-24-05

Comments:

HUB # TEST: HE-04 ATT123080

CONFIRMED TAMPERED WITH

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

BY

ACCOUNT HISTORY SUMMARY

1-24-05

Tech #3455

DISCLAIMER ON BOTTOM OF BOX! NOTICE THAT IF
 SERVICE DEVICE IS A CIVIL INSTALLING THIS
 MODIFYING OR ALTERING IT IN ANY WAY MAY SUBJECT YOU
 TO CIVIL OR CRIMINAL PENALTIES. CHECK WITH YOUR LOCAL
 CABLE COMPANY.